Toe of Campo Cielo Landslide that has Engulfed a Road in the Community

Recently Formed Fractures at the Landslide Toe


Terminus of Landslide…Backyard of Local Resident that has already Evacuated his Family
Continued Accumulation of Mud from the Toe

Landslide Toe in Vicinity of another Home at High Risk
Note Orientation of Home Recently Constructed on Landslide Toe